

# MotionController v1.12.629

\* Release date: 20-12-2017

## Compatibility:

\* MotionManager: 1.12.9.MM

### \* Actuator identity file:

- o AIF\_02\_CH1000S.AID for CyberHoist, 1000kg
- o AIF\_03\_CH0500S.AID for CyberHoist II, 500kg
- o AIF\_04\_CH2000D.AID for CyberHoist, 2000kg
- o AIF\_20\_CT2000X.AID for CyberTrolley, 2000kg
- o AIF\_40\_CW0250S.AID for CyberWinch, 250kg, single-wire
- o AIF\_41\_CW0250D.AID for CyberWinch, 250kg, double-wire

\* Drive firmware files: Upgrade\_FL\_scib.DR1 and TMS\_No1.DR2

## ENHANCEMENTS & NEW FEATURES

Ref#	Description
<u>864</u>	<b>[CM-360] the application can't handle a 930 error</b> Use 'Set target Position' to apply 3d model position
<u>899</u>	<b>[CM-395] Implement Object Direct Control - Motion Controller part</b>
<u>928</u>	<b>[CM-424] go to normal mode after object direct control</b>
<u>1156</u>	<b>[CM-658] Loadcell flow for 2 loadcells</b> Motion Controller is able to handle 2 load cells with 2 sensors each. The self-weight of a hoist is subtracted automatically.
<u>1270</u>	<b>[CM-779] Winch limitswitches</b> Winches received new position limit switches



<u>1347</u>	<b>[CM-856] Auto-detect if CyberHoist II is self-climbing or not</b>
<u>1407</u>	<b>[CM-917] Strip coreData for Setup and Show</b>
<u>1454</u>	<b>[CM-965] Error 941 cannot be released</b> True. The issue requires new model and object settings.
<u>1455</u>	<b>[CM-966] Error 930</b> Use 'Set target Position' to apply 3d model position
<u>1467</u>	<b>[CM-978] Keep MCErrror log clean</b>
<u>1475</u>	<b>[CM-986] Usage of K5 serialNrMotioncontroller, K6 serialNrInitialMotioncontroller unclear</b> Changed to individual serial numbers and names
<u>1477</u>	<b>[CM-988] CyberHoist II (CH0500S), self-climbing</b>
<u>1478</u>	<b>[CM-989] Integrate new Actuator Types CH1000S, CH2000D</b>
<u>1525</u>	<b>[CM-1036] Cleanup for AIF, p-list, EEPROM Data</b>
<u>1526</u>	<b>[CM-1037] DOC with Trolley exceeds Speed</b> Fixed
<u>1532</u>	<b>[CM-1043] Major.Minor Number for Version</b>
<u>1533</u>	<b>[CM-1044] Release of Safe Direction</b>
<u>1539</u>	<b>[CM-1050] E491 caused by Power Distro</b> Drive STO cannot be cleared. A missing phase could be the cause. Check voltage on power supply. Defective drive, motion controller or interconnection. Repair.
<u>1546</u>	<b>[CM-1057] E804 drive is missing an incoming phase</b> The drive is missing an incoming phase. Check mains / incoming power / repair. (Drive error code: 17)



<u>1555</u>	<b>[CM-1066] Cleanup for AIF, p-list, EEPROM Data</b>
<u>1549</u>	<b>[CM-1060] E839 (W phase over current)</b> Current of incoming phase L3 is too high. Check mains voltage (>190 V AC), load and duty cycle. (Drive error code: 84)
<u>1561</u>	<b>[CM-1072] Use 925/926 to synchronize all class 1/2/3 stops</b> Objects will stop synchronously in case one or several actuators have an error.
<u>1562</u>	<b>[CM-1073] New Actuator Types CH1000S, CH2000D</b>
<u>1563</u>	<b>[CM-1074] Cleanup Communication Protocols</b>
<u>1564</u>	<b>[CM-1075] Cleanup Communication Protocols</b>
<u>1567</u>	<b>[CM-1078] Actuator Position Limits exceeded</b>
<u>1569</u>	<b>[CM-1080] How to determine startTorqueMultiplier?</b> The factor has been re-fitted to all CyberHoist II and CyberTrolley. This results in a smoother start of motion.
<u>1575</u>	<b>[CM-1086] When maintenance mode ends, drive parameters are reset</b>
<u>1584</u>	<b>Processing MaintenanceControls 0x4000</b>
<u>1603</u>	<b>Equal angular speed for different objects in Direct Object Control</b> Not applicable
<u>1639</u>	<b>When maintenance mode starts, drive params are reset</b> Works correct
<u>1641</u>	<b>Joystick overrule and error 928</b>
<u>1642</u>	<b>CH0500S is very noisy at low load, speed</b> CyberHoist II, 500kg received new values for velocity and position control loops.
<u>1651</u>	<b>Review margins on errors 930 and 938</b>



<u>1662</u>	<b>Update object DC interval (prevent E496)</b>
<u>1689</u>	<b>E941 during Object Control</b>

## BUGFIXES

Bug#	Description
<u>1248</u>	<b>[CM-757] ADC readout frozen</b> The A/D converters for load cells produces no read errors.
<u>1313</u>	<b>[CM-822] Progress Pop-up while Updating Drive Firmware has wrong Text</b> Fixed
<u>1585</u>	<b>Unable to update p-lists for winches</b> Fixed
<u>1600</u>	<b>Handling of Errors in Objects under direct Object Control</b>
<u>1492</u>	<b>[CM-1003] Actuator Serial No. gets lost</b> Fixed
<u>1509</u>	<b>[CM-1020] Appearance of error 927 (object direct control)</b> Uses different margins now and shall appear less often.
<u>1571</u>	<b>[CM-1082] E608 does not use margin</b> Following errors in control loop may lead to such errors. The check is on target values, not current values



## KNOWN BUGS & LIMITATIONS

Bug#	Description
<u>497</u>	<b>Drive com error</b> When powering up a actuator for the fist time may cause in a Drive com error. Unplugging the power for no longer then 2 seconds fixes this issue.

**Notes: n/a**

