

Masterbox firmware v1.12.600

* Release date: 1 feb 2018

Compatibility:

- * **Desk Firmware:** 10001.dsk and 10002.dsk
- * **MotionManager** 1.12.9.MM
- * **Motioncontroller firmware:** 1.12.629.MC
- * **Actuator identity file:** CH500.Plist
- * **Motioncontroller Drive firmware:** TMS_No1.DR1 and Upgrade_FL_scib.DR2

ENHANCEMENTS & NEW FEATURES

Ref#	Description

BUGFIXES

Bug#	Description
<u>702</u>	Monitoring the power supply Monitoring the power supply of the 2nd encoder used at C-Trolley is no longer producing persistent errors E830 and E30.



KNOWN BUGS & LIMITATIONS

Bug#	Description
<u>497</u>	Drive com error When powering up a actuator for the fist time may cause in a Drive com error. Unplugging the power for no longer then 2 seconds fixes this issue.

Notes:

n/a

